



1. Hold down the USER/PRG key, then press the RST key once, and release the USER/PRG key.
2. Open the computer Device Manager and check the device port.



3. Open the folder, Right click "Flash.bat", select "Edit", change COM to the port seen in the previous step.



4. "Ctrl + S", Save the file.
5. Left click Flash.bat and wait for the program to upload.